

Plasmarc Accessories



Remote Hand Switch



Deluxe Torch Guide Kit



Basic Torch Guide Kit

Remote Hand Switches

- Allows the operator to start and stop the cutting process with a remote switch
- Used primarily for mechanized cutting and is included in the mechanized Plasmarc packages

PT-20AMX.....	680982
ESP-150/ESP-200.....	2075600
PT-21AMX.....	0558003612
PT-37, 25 ft. (7.6 m).....	0558008349
PT-37, 50 ft. (15.2 m).....	0558009277


Torch Guide Kits

- Includes attachments for circle and straight line cutting on ferrous and non-ferrous metals

Deluxe: 1-3/4 in. (44.5 mm) 42 in. (106 cm) radius... 0558003258
 Basic: 1-3/4 in. (44.5 mm) 28 in. (71 cm) radius... 0558002675



Torch shown with Plasmits



Plasma Flow Measuring Kit

Plasma Flow Measuring Kit

- Valuable troubleshooting tool
 - Allows measurement of actual plasma gas flow through torch
- Plasma flow measuring kit 0558000739

Plasmits

- Special flexible shields attach around the head of a plasma cutting torch to provide added protection against heat and molten metal
- Recommended for heavy-duty plasma gouging applications

PT-121	
75° torch	20742
90° torch	20801
Mechanized torch	20802
PT-25	
90° torch	20801
175° torch	20805
PT-26	
70° torch	0558006717
90° torch	0558006718
PT-17A manual torch	20803
PT-32EH	0558007989

Leather Sheath

- A leather sheath to protect torch leads from abrasion and molten metal
- Particularly recommended for plasma gouging
- For use with any ESAB Plasmarc torch

Leather Sheath with Snaps

10 ft. (3 m)	20812
25 ft. (7.6 m)	0558002921
50 ft. (15.2 m)	0558002922

Replacement Bushings

- Used for torch guide kits

Adaptor

PT-23/27 bushing	TJ2225
PT-25 bushing.....	TJ2230
PT-31XL bushing	TJ2228
PT-32 bushing.....	0558003257

Torch Coolant

50% EG torch coolant.....	0560950312
---------------------------	------------

Utility Cart for PowerCut Series

- This enables easy transport of the PowerCut Series Machines

Utility cart..... 0558007898



Utility Cart for PowerCut Series